

# **BCM**

# **Product Change Notice**

PCN Type: □HW/SYS	5/Kit ■BIOS/LAN/F\	W □Package	e/Label □Dri	ver/OS	□Acc.	□Others	Page: <u>1</u> of <u>1</u>
PCN Number: 70601-B1-006 Revision: A Date of Publication: 08/28/2014					2014		
PRODUCT NAME	PRODUCT PART#	OLD — RE	<b>V.</b> — NEW			REVISION	TYPE
BC35Q	70601-C	1.03	1.06	BIOS			

#### **REASON OF CHANGE:**

Fix an intermittent cold boot LAN detection issue.

#### **DESCRIPTION OF CHANGE:**

File name: 70601106.ROM Message: BC35Q BIOS VER 1.06

Date: 08/14/2014 Checksum: 2D8F hex

Flash Utility: AMI Firmware Update Utility v4.15 (afudos.exe)

## IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal or regulation implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE		
Specification	NO	
Packaging	NO	
Labeling	NO	
BIOS	YES	
Driver	NO	
Hardware	NO	

## **CUT IN DATE:**

Date: 09/15/2014

OR **Lot#**:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	Χ		
In Process	Х		
Finished Goods	Х		
RMA		Х	

This PCN had been QUALIFIED and APPROVED by BCM Engineering Department on 08/19/2014.

#### **APPROVED BY**

VP OF SALES	<approved></approved>	08/28/2014
-------------	-----------------------	------------

Signature Date

Doc#: F-G0-0-005G