

## **BCM**

# **Product Change Notice**

PCN Type: UHardwa	are ■BIOS/Firmwa	re ⊔Package	e/Label ⊔Dri	ver ⊔OS	⊔Others	Page: <u>1</u> of <u>1</u>
PCN Number: 7087	Revision: A		Date of Publication: 06/13/2013			
PRODUCT NAME	PRODUCT PART#	OLD — RE	<b>V.</b> — NEW		REVISION	ON TYPE
BC77Q	70871-C	1.00	1.01	BIOS		

#### **REASON OF CHANGE:**

- 1) Add CMOS Checksum Error message after CMOS is cleared. This is a notification message that will only appear immediately after either the BIOS has been cleared or the BIOS has been updated. This has been added because this message is not generated automatically in the new AMI UEFI BIOS codebase.
- 2) Fine tune the CPU temperature reading under BIOS Hardware Monitor display.

#### **DESCRIPTION OF CHANGE:**

File Name: 70871211.bin

BIOS Message: BC77Q (70871) BIOS Ver 1.01

Version: 1.01 Date: 5/13/2013 Checksum: 2513 hex

Flash Utility: AMI Firmware Update Utility v2.33 (AFUDOS)

#### **IMPACT OF CHANGE AND RECOMMEND ACTION:**

This change has been thoroughly evaluated to ensure that there are no quality, reliability or function implications to our customers.

BCM is not recommending customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE		
Specification	NO	
Packaging	NO	
Labeling	NO	
BIOS	YES	
Driver	NO	
Hardware	NO	

#### **CUT IN DATE:**

Date: 08/05/2013

OR **Lot#**:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	Χ		
In Process	Х		
Finished Goods		Х	
RMA		Х	

This PCN had been QUALIFIED and APPROVED by BCM Engineering Department on 06/05/2013.

### **APPROVED BY**

VP OF SALES	<approved></approved>	06/13/2013
-------------	-----------------------	------------

Signature Date

Doc#: F-G0-0-005F