



# BCM

## Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

<b>PCN Number:</b> 71001-H1-002		<b>Revision:</b> A		<b>Date of Publication:</b> 08/22/2014
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
MX1900J	71001-IA	1.0	1.1	Hardware

**REASON OF CHANGE:**  
Resolve the Rocker switch button timing issue for On/Off

**DESCRIPTION OF CHANGE:**

- 1) Remove C1789 and C1790 components.
- 2) Change SC29 value to 10uF.

**IMPACT OF CHANGE AND RECOMMEND ACTION:**

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or thermal implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**

Date: 08/29/2014  
OR  
Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods	X		
RMA	X		

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 08/22/2014.

**APPROVED BY**

<b>VP OF SALES</b>	<APPROVED>	08/22/2014
--------------------	------------	------------

Signature

Date