



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 71142-B1-003		Revision: A		Date of Publication: 05/08/2017
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX3160N	71142-IA	1.01	1.02	BIOS

REASON OF CHANGE:

To address an issue where USB 3.0 devices may experience intermittent link-train issues during Warm Reboot Cycling (reference Intel Doc: 569674).

DESCRIPTION OF CHANGE:

File name: 71142102.ROM
 Message: MX3160N #71142 BIOS V1.02
 Version#: 1.02
 File Date/ Time: 04/20/2017 6:25:30 AM
 Checksum: 6180 hex

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal, driver or regulation implications to our customer.

BCM is not recommending our customer to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

CUT IN DATE:

Date: July, 2017
 OR
 Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods		X	
RMA	X		

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 05/04/2017.

APPROVED BY

VP OF SALES	<APPROVED>	05/08/2017
--------------------	------------	------------

Signature

Date