BCM

Product Change Notice

PCN Type: ■Hardware □BIOS/Firmware □Package/Label □Driver □OS □Others   Page: 1 of 1

PCN Number: 71391-H1-003/ 69282-S1-003/ 69270-S1-002/ 69294-S1-001/ 69295-S1-001/ 69298-S1-001		**Revision:** B		**Date of Publication:** 04/11/2014
PRODUCT NAME	**PRODUCT PART#**	OLD — **REV.** — NEW		**REVISION TYPE**
MX61H	71391-C	1.1	1.2	Hardware
BOX-MX61H-G1	69282	1.1	1.2	
BOX-61H-SST41	69270	1.0	1.1	
	69294	1.0	1.0	
BOX-61H-SST44	69295	1.0	1.0	
BOX-61H-SST44A	69298	1.0	1.0	

REASON OF CHANGE:

Improve compatibility with a broader range of 5V LVDS LCD Panels through the JLVDS1 port on the MX61H board.

DESCRIPTION OF CHANGE:

1) Remove resistor on location LVR2.
2) Change resistor to 1KΩ on location LVR5.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional and certificate implications to our customers.

BCM is not recommending customers to perform additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: 06/02/2014
  OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 03/27/2014.

APPROVED BY

VP OF SALES	<APPROVED>	04/11/2014
	Signature	**Date**