BCM

Product Change Notice

PCN Type: ■HW/SYS/Kit ☐BIOS/LAN/FW ☐Package/Label ☐Driver/OS ☐Acc. ☐Others   Page: _1_ of _1_

PCN Number: H192202		Revision: B		Date of Publication: 05/28/2019
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX110H	71152-IA	1.2	1.3	Hardware
MX110HD	71591-IA	3.0	3.1	
MX3160N	71142-IA	2.1	2.2	
MX3350N	71521-IA	2.1	2.2	
RX110H	71172-IA	2.0	2.1	

REASON OF CHANGE:
To address the CVE-2017-15361 security issue pertaining to the Trusted Platform Module (TPM) also referred to as "Return of Coppersmith's Attack" (ROCA). Please refer to ADV170012 Security Advisory by Microsoft for more information.   https://portal.msrc.microsoft.com/en-US/security-guidance/advisory/ADV170012

DESCRIPTION OF CHANGE:
Change Trust Platform Module (TPM) 2.0 from FW: 5.62 to 5.63.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal and regulation implications to our customer.
BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: Nov, 2019
  OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on March, 2019.
This PCN had been **APPROVED** by BCM Procurement Department on May, 2019.

APPROVED BY

VP OF SALES	<APPROVED>	05/28/2019
	Signature	**Date**

Doc#：F-G0-0-006A