BCM

Product Change Notice

PCN Type: ■HW/SYS/Kit □BIOS/LAN/FW □Package/Label □Driver/OS □Acc. □Others   Page: 1 of 1

PCN Number: 70961-H1-007/ 70962-H1-004		Revision: B		Date of Publication: 03/28/2017	
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE	
MX280NI	70961-IA	1.5A	1.6	Hardware	
	70962	1.2A	1.3		

REASON OF CHANGE:

Improve reliability in some corner cases.

DESCRIPTION OF CHANGE:

1) Change PR137 and PR154 from 100K to 20K ohm resistor.
2) Change PC87 and PC96 from 1uF/16V to 0.1uF/16V capacitor.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal or regulation implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: March, 2017
  OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 03/22/2017.

APPROVED BY

VP OF SALES	<APPROVED>	03/27/2017
	Signature	Date

Doc# ：F-G0-0-005G