



BCM

Product Change Notice

PCN Type: ☒ HW/SYS/Kit ☐ BIOS/LAN/FW ☐ Package/Label ☐ Driver/OS ☐ Acc. ☐ Others Page: 1 of 1

PCN Number: P264301		Revision: A		Date of Publication: 10/21/2026
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX370QD	71635-IA	2.0	2.1	Hardware

REASON OF CHANGE:

PANJIT PJQ4404P MOSFET has supply constraint.

DESCRIPTION OF CHANGE:

Add PANJIT PJQ4524P MOSFET to Approved Vendor List (AVL) at location PQ129 and change resistor location PR121 from 24.9Ω to 49.9Ω.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, or thermal implications. BCM is not recommending customers to perform additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: April, 2027
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Implementation/ Rework	As Is	Scrap
New Production Orders	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on October, 2026.
This PCN had been **APPROVED** by BCM Procurement Department on October, 2026.

APPROVED BY

VP OF SALES	<APPROVED>	10/21/2026
--------------------	------------	------------

Signature

Date

Doc#: F-G0-0-007B