BCM

Product Change Notice

PCN Type: ■Hardware ☐BIOS/Firmware ☐Package/Label ☐Driver ☐OS ☐Others

PCN Number: 70541-H1-005/ 70611-H1-005/ 70651-H1-004/ 70653-H1-003/ 70731-H1-003		Revision: A		Date of Publication: 08/29/2013
PRODUCT NAME	**PRODUCT PART#**	OLD ━ REV. ━ NEW		**REVISION TYPE**
RX965Q	70541-C	1.3	1.3	Hardware AVL (approved vendor list)
RX965QV	70611-C	1.2	1.2	
RX35Q	70651-C	1.2	1.2	
RX35Q-P	70653-C	1.2	1.2	
RX35Q-ET	70731	1.1	1.1	

REASON OF CHANGE:

Add a new PCIex16 socket to the approved vendor list (AVL) due to Kortak going out of business.

DESCRIPTION OF CHANGE:

Add WinWin PCI-E x16 slot to Approved vendor list.

Current Kortak PCI-E x16

New WinWin PCI-E x16 slot

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal or driver implications to our customers.

BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: Running Changes
   OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 08/29/2013.

APPROVED BY

VP OF SALES	<APPROVED>	08/29/2013
	Signature	**Date**