



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver OS Others Page: 1 of 1


PCN Number: 70871-H1-002		Revision: A		Date of Publication: 04/08/2014
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
BC77Q	70871-C	1.0	1.1	Hardware

REASON OF CHANGE:

Prevent the lever handle on the CPU socket from damaging the traces on the motherboard during installation of the CPU.

DESCRIPTION OF CHANGE:

Add Mylar underneath the CPU socket lever handle.



IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal, or regulatory implications to our customers.

BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: 09/15/2014

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 03/20/2014.**APPROVED BY**

VP OF SALES	<APPROVED>	04/08/2014
-------------	------------	------------

Signature

Date