



Product Change Notice

PCN Number: P210604		Revision: A		Date of Publication: 02/12/2021	
PRODUCT NAME	PRODUCT PART#	OLD — RE	V. — NEW	REVISION TYPE	
CM-APL-N3350-A1R	ECM-APL-N3350-A	A1	A1	Hardware	
	1R	1.40	1.50	BIOS	
REASON OF CHANG	SE:				
Realtek ALC892 audio	codec will be End of	Life.			
DESCRIPTION OF C	HANGE:				
Change to Realtek ALC	C888S audio codec.				
MPACT OF CHANG	E AND RECOMMEN	D ACTION:			
- - - - - - - - - -	***				
his change has been	thoroughly evaluate	d to ensure the	at there is no	o quality, reliability or thermal implications t	
•					
-					
ustomer.					
sustomer. BCM is not recommer	-	•	•	ication of this changes if using Windows 10	
sustomer. BCM is not recommer	-	•	•	ication of this changes if using Windows 10 nding to update the audio driver.	
BCM is not recommer Iriver. If customer is u	using other Operating	•	•		
AFFECTED BY THIS	using other Operating	•	•		
AFFECTED BY THIS	using other Operating S CHANGE NO	•	•		
Customer. BCM is not recommer driver. If customer is un AFFECTED BY THIS Specification Packaging	using other Operating S CHANGE NO NO	•	•		
AFFECTED BY THIS Specification Labeling	using other Operating S CHANGE NO NO NO	•	•		
AFFECTED BY THIS Specification Packaging BIOS	S CHANGE NO NO NO YES	•	•		
AFFECTED BY THIS Specification Packaging BIOS Driver	S CHANGE NO NO NO YES NO	•	•		
AFFECTED BY THIS Specification Packaging BIOS Driver Hardware	S CHANGE NO NO NO YES	•	•		
AFFECTED BY THIS Specification Packaging BIOS Driver	S CHANGE NO NO NO YES NO	•	•		
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE:	S CHANGE NO NO NO YES NO	•	•		
AFFECTED BY THIS Specification Packaging BIOS Driver Hardware CUT IN DATE: Date: May, 2021	S CHANGE NO NO NO YES NO	•	•		
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: May, 2021 OR	S CHANGE NO NO NO YES NO	•	•		
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: May, 2021	S CHANGE NO NO NO YES NO	•	•		
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: May, 2021 OR Lot#:	S CHANGE NO NO NO YES NO YES	g system, BCM	•		
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: May, 2021 OR Lot#:	S CHANGE NO NO NO YES NO YES	g system, BCM	•		
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: May, 2021 OR Lot#:	S CHANGE NO NO NO YES NO YES	g system, BCM	is recomme		
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: May, 2021 OR -ot#: Cut in date is based of	S CHANGE NO NO NO YES NO YES	g system, BCM	is recomme	nding to update the audio driver.	
AFFECTED BY THIS Specification Packaging BIOS Driver Hardware CUT IN DATE: Date: May, 2021 OR ot#: Cut in date is based of Parts Disposition	S CHANGE NO NO NO YES NO YES on the current foreca Rework	g system, BCM	is recomme	nding to update the audio driver.	
AFFECTED BY THIS Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: May, 2021 OR Lot#: Cut in date is based of Parts Disposition New Order	S CHANGE NO NO NO YES NO YES On the current foreca Rework X	g system, BCM	is recomme	nding to update the audio driver.	

APPROVED BY

VP OF SALES	<approved></approved>	02/12/2021