



Product Changes Notice

PCN Number: HB18	1902	Revision: B		Date of Publication: 05/09/2018
PRODUCT NAME	PRODUCT PART#	OLD — RE	V. — NEW	REVISION TYPE
MX110HD	71591-IA	1.0	3.0	Hardware
		(71472-IA)	(71591-IA)	
		1.02 (71472-IA)	1.00	BIOS
EASON OF CHAN	GE:	(71472-IA)	(71591-IA)	
()				
-	power input to be wid	-		
-	Platform Module (TPN	-		
-	silkscreen typographie			a a at
4) Comply with	the latest airfreight re	egulations for I	battery trans	port.
DESCRIPTION OF C	HANGE:			
1) Update the [DC input range to 12V	~ 24V.		
	Printer Terminal (LPT			
-	TPM 2.0 chip.			
-	•			
Update PCB	SIIKSCI EEII.			
5) Add UN3091 MPACT OF CHANG his change has been	battery warning labe	D ACTION:	at there are i	no quality and functional implications
5) Add UN3091 MPACT OF CHANG This change has been customers.	battery warning labe	D ACTION: d to ensure tha		
5) Add UN3091 MPACT OF CHANG This change has been customers.	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfo	D ACTION: d to ensure tha		
5) Add UN3091 IMPACT OF CHANG This change has been customers. BCM is recommendin	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfo	D ACTION: d to ensure tha		
5) Add UN3091 MPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfo IS CHANGE	D ACTION: d to ensure tha		
5) Add UN3091 IMPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfo IS CHANGE YES	D ACTION: d to ensure tha		
5) Add UN3091 MPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perform IS CHANGE YES NO	D ACTION: d to ensure tha		
5) Add UN3091 MPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfor IS CHANGE YES NO NO	D ACTION: d to ensure tha		
5) Add UN3091 IMPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfor IS CHANGE YES NO NO YES	D ACTION: d to ensure tha		
5) Add UN3091 IMPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfor IS CHANGE YES NO NO YES YES	D ACTION: d to ensure tha		
5) Add UN3091 MPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: Nov, 2018	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfor IS CHANGE YES NO NO YES YES	D ACTION: d to ensure tha		
5) Add UN3091 MPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: Nov, 2018 OR	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfor IS CHANGE YES NO NO YES YES	D ACTION: d to ensure tha		
5) Add UN3091 IMPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: Nov, 2018 OR Lot#:	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfore IS CHANGE YES NO NO YES YES YES	D ACTION: d to ensure the		
5) Add UN3091 IMPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: Nov, 2018 OR Lot#: 'Cut in date is based	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfore IS CHANGE YES NO NO YES YES YES YES On the current forecast	D ACTION: d to ensure the	qualification	of this change.
5) Add UN3091 IMPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: Nov, 2018 OR Lot#:	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfore IS CHANGE YES NO NO YES YES YES	D ACTION: d to ensure the orm additional st. As Is	qualification	
5) Add UN3091 MPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: Nov, 2018 OR Lot#: Cut in date is based Parts Disposition	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfore IS CHANGE YES NO NO YES YES YES YES On the current forecast	D ACTION: d to ensure the rm additional st. As Is X	qualification	of this change.
5) Add UN3091 MPACT OF CHANG This change has been customers. BCM is recommendin AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: Nov, 2018 OR Lot#: Cut in date is based Parts Disposition New Order	battery warning labe E AND RECOMMEN In thoroughly evaluate Ing customers to perfore IS CHANGE YES NO NO YES YES YES YES On the current forecast	D ACTION: d to ensure the orm additional st. As Is	qualification	of this change.

APPROVED BY

|--|