



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: P234001		Revision: A		Date of Publication: 10/03/2023
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
RX110H	71172-IA	1.01	1.02	LAN Firmware
MX110H	71152-IA	1.01	1.02	
MX3160N	71142-IA	1.01	1.02	

REASON OF CHANGE:
Addressing various errata on Intel i210-AT Ethernet controller.

DESCRIPTION OF CHANGE:
Change Intel i210-AT Ethernet controller's firmware from version 3.16 to 3.25.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional and thermal implications to our customer.
BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
LAN	YES
Driver	NO
Hardware	NO

CUT IN DATE:
Date: December, 2023
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 09/29/2023.
This PCN had been **APPROVED** by BCM Procurement Department on October, 2023.

APPROVED BY

VP OF SALES	<APPROVED>	10/03/2023
--------------------	------------	------------

Signature

Date