

BCM

Product Change Notice

PCN Type: ■HW/SYS/Kit □BIOS/LAN/FW □Package/Label □Driver/OS □Acc. □Others Page: <u>1</u> of <u>1</u>

PCN Number: 71131-H1-002		Revision: A		Date of Publication: 05/26/2016	
PRODUCT NAME	PRODUCT PART#	OLD — RE	V. — NEW	REVISION TYPE	
MX170QD	71131-IA	1.0	1.1	Hardware	


REASON OF CHANGE:

To make the M.2 connectors insertion angle more convenient for inserting M.2 cards.

DESCRIPTION OF CHANGE:

Change M.2 connector to support a higher insertion angle.

Original New



IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal, or regulatory implications to our customers.

BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE				
Specification	NO			
Packaging	NO			
Labeling	NO			
BIOS	NO			
Driver	NO			
Hardware	YES			

CUT IN DATE:

Date: August, 2016

OR **Lot#**:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		Х	
In Process		Х	
Finished Goods		Х	
RMA		Х	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 05/26/2016.

APPROVED BY

VP OF SALES	<approved></approved>	05/26/2016	
-------------	-----------------------	------------	--

Signature Date

Doc#: F-G0-0-005G