

BCM


Product Change Notice

 $PCN \ Type: \blacksquare HW/SYS/Kit \ \Box BIOS/LAN/FW \ \blacksquare Package/Label \ \Box Driver/OS \ \Box Acc. \ \Box Others \qquad Page: \ \underline{1} \ of \ \underline{1}$

PCN Number: 71001-H1-004		Revision: A		Date of Publication: 11/06/2014	
PRODUCT NAME	PRODUCT PART#	OLD — RE	V. — NEW	REVISION TYPE	
MX1900J	71001-IA	1.1A	1.2	Hardware/ Package	


REASON OF CHANGE:

- 1) Pre-install screws on M2 standoffs based on customer feedback.
- 2) Change the shipping carton configuration to optimize pallet shipments.
- 3) Improve internal power efficiency.
- 4) Correct I/O shield icon positioning.



DESCRIPTION OF CHANGE:

- 1) Pre-install screws on M2 standoffs.
- 2) Change bulk package carton to fit 18 units per carton.
- 3) Change to new power IC.
- 4) Correct I/O shield icon positioning per below.



IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal, or regulation implications to our customers.

BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE		
Specification	NO	
Packaging	YES	
Labeling	NO	
BIOS	NO	
Driver	NO	
Hardware	YES	

CUT IN DATE:

Date: 12/01/2014

OR **Lot#**:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		Х	
Finished Goods		X	
RMA		Х	

This PCN had been QUALIFIED and APPROVED by BCM Engineering Department on 11/06/2014.

APPROVED BY

VP OF SALES <approved> 11/06/2014</approved>
--

Signature Date

Doc#: F-G0-0-005G