

BCM

Product Change Notice

PCN Type: ■HW/SYS	s/Kit ■BIOS/LAN/F	W ■ Package	e/Label □	Driver/OS	□Acc.	□Others	Page: <u>1</u> of <u>1</u>
PCN Number: H174403		Revision: A		Date of	Date of Publication: 11/01/2017		
PRODUCT NAME	PRODUCT PART#	OLD — RE	V. — NEW			REVISION	TYPE
MX3350N	71521-IA	1.0	2.0	Hardwa	are		
		1.00	2.10	BIOS			
						•	

REASON OF CHANGE:

- 1) Update specification.
- 2) Address Intel® Celeron® Processor N3350 LPC issue
- 3) Comply the latest air freight regulation for labeling requirements.

DESCRIPTION OF CHANGE:

- 1) Add Trusted Platform Module (TPM) 2.0.
- 2) Add LPC bus level circuit.
- 3) Add UN3091 labels on the box outside.
- 4) Update the BIOS to revision 2.10.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or thermal implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE				
Specification	YES			
Packaging	NO			
Labeling	YES			
BIOS	YES			
Driver	YES			
Hardware	YES			

CUT IN DATE:

Date: Mar, 2018

OR Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	Х		
In Process		Х	
Finished Goods		X	
RMA		Х	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 11/01/2017.

APPROVED BY

VP OF SALES	<approved></approved>	11/01/2017

Signature

Date

Doc#: F-G0-0-005G