



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others Page: 1 of 1

PCN Number: 71251-H1-002		Revision: A		Date of Publication: 04/20/2011
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX45GM2	71251-C	1.0	2.0	Hardware Revision

REASON OF CHANGE:

- 1) To meet UL 60950-1 Second Edition.
- 2) Realtek audio codec ALC888 will be EOL.

DESCRIPTION OF CHANGE:

- 1) Add fuse on +5V on DVI connector.
- 2) Change the fuse for USB ports from 1.6A to 1.1A.
- 3) Add Realtek audio codec ALC886 in AVL.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality and reliability implications to our customers.

If the customer is using Microsoft® Windows® OS, BCM recommends updating audio driver to version R2.53 (5.10.0.6215) or above. It is recommended that the customer evaluates this new hardware changes to ensure smooth transition.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: 08/15/2011
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 04/19/2011.

APPROVED BY

CUSTOMER/ VP OF SALES	<APPROVED>	04/20/2011
----------------------------------	------------	------------

Signature

Date