



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others

Page: 1 of 1

PCN Number: 71211-H1-003		Revision: A		Date of Publication: 09/10/2010
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX45GM	71211-C	1.1	1.2	Hardware Revision

REASON OF CHANGE:
 Improve 667MHz FSB (PC2-5300) memory compatibility

DESCRIPTION OF CHANGE:

1. Change 330 ohm to 10K ohm resistor on PR55
2. Remove 0 ohm resistor on R663
3. Remove 0 ohm resistor on SR99
4. Add 0 ohm resistor on SR107

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.

BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: 09/13/2010
 OR
 Lot#:

*Cut in date is based on the current forecast.

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 09/08/2010.

APPROVED BY

CUSTOMER/ VP OF SALES	<APPROVED>	09/10/2010
----------------------------------	------------	------------

Signature

Date