



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver OS Others Page: 1 of 1

PCN Number: 71391-H1-002/ 71393-H1-001		Revision: A		Date of Publication: 11/27/2013
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW	REVISION TYPE	
MX61H	71391	1.0	1.1	Hardware
MX61H-HW	71393	0.1	1.0	

REASON OF CHANGE:
Adjust the LED brightness of the yellow color LED (Link Activity) on LAN1 & LAN2 ports when the MX61H is in the power state S5.

DESCRIPTION OF CHANGE:
Add the resistors on L1C2 and L2C2.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal or regulation implications to our customers.
BCM is not recommending additional qualification of these changes on the unit.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:
Date: 01/06/2014
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 10/30/2013.

APPROVED BY

VP OF SALES	<APPROVED>	11/27/2013
--------------------	------------	------------

Signature

Date