



# BCM

## Product Change Notice

PCN Type:  Hardware  BIOS/Firmware  Package/Label  Driver  OS  Others Page:  1  of  1

<b>PCN Number:</b> 70821-H1-004/ 70822-H1-003/ 71321-H1-005/ 71322-H1-003/ 71323-H1-004		<b>Revision:</b> A		<b>Date of Publication:</b> 04/01/2013
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	<b>OLD — REV. — NEW</b>		<b>REVISION TYPE</b>
MX67QMD	70821-C	2.0	2.0*/ 2.1	Hardware
MX67QMD-LC	70822	1.1	1.2	
MX67QM	71321-C	1.2	1.3	
MX67QMU	71322-C	1.1	1.2	
MX67QM-QC	71323	1.1	1.2	

### REASON OF CHANGE:

- 1) To prevent lost CMOS due to battery contact disruption from vibration or accidental contact.

### DESCRIPTION OF CHANGE:

- 1) \*Apply Acetate cloth tape on work in process and warranty returned goods.



Apply heat shrink tubing on new production.



**IMPACT OF CHANGE AND RECOMMEND ACTION:**

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal, driver or UL certification implications to our customers.

BCM is not recommending customers to perform additional qualification of these changes.

<b>AFFECTED BY THIS CHANGE</b>	
<b>Specification</b>	NO
<b>Packaging</b>	NO
<b>Labeling</b>	NO
<b>BIOS</b>	NO
<b>Driver</b>	NO
<b>Hardware</b>	YES

**CUT IN DATE:**

Date: 04/01/2013

OR

Lot#:

\*Cut in date is based on the current forecast.

<b>Parts Disposition</b>	<b>Rework</b>	<b>As Is</b>	<b>Scrap</b>
<b>New Order</b>	X		
<b>In Process</b>	X*		
<b>Finished Goods</b>	X*		
<b>RMA</b>	X*		

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 04/01/2013.

**APPROVED BY**

<b>VP OF SALES</b>	<APPROVED>	04/01/2013
--------------------	------------	------------

**Signature**

**Date**