



Product Change Notice

| PCN Type: ■HW/SYS | S/Kit □BIOS/LAN/F | <i>W</i> □Package | /Label □Dr | river/OS □Acc. □Others Page: <u>1</u> of <u>1</u> | |
|--------------------------|------------------------------|-------------------|-----------------|--|--|
| PCN Number: 70932-H1-003 | | Revision: A | | Date of Publication: 02/12/2015 | |
| PRODUCT NAME | PRODUCT PART# | OLD - RE | V. — NEW | REVISION TYPE | |
| MX87QD | 70932-C | 1.2 | 1.3 | Hardware | |
| | | | | | |
| REASON OF CHANG | E: | | | | |
| | | | | | |
| Improve compatibility | for 5V LVDS display | paneis. | | | |
| DESCRIPTION OF CI | HANGE: | | | | |
| | | | | | |
| 1) Remove part | | | | | |
| 2) Change resiste | or to $1k\Omega$ on location | LVR6. | | | |
| IMPACT OF CHANGE | AND RECOMMEN | | | | |
| | | D Aorion. | | | |
| This change has been | thoroughly evaluate | d to ensure tha | at there are r | no quality, reliability, functional, driver or thermal | |
| implications to our cu | | | | | |
| | | | | | |
| BCM is not recommer | nding our customers | to perform add | ditional quali | ification of these changes. | |
| [| | | | | |
| AFFECTED BY THIS | | | | | |
| | NO | | | | |
| | NO | | | | |
| | NO | | | | |
| - · | NO | | | | |
| | NO | | | | |
| | YES | | | | |
| CUT IN DATE: | | | | | |
| Date: May, 2015 | | | | | |
| OR | | | | | |
| Lot#: | | | | | |
| | | | | | |
| *Cut in date is based of | on the current forecas | st. | | | |
| Parts Disposition | Rework | As Is | | Scrap | |
| New Order | | X | | | |
| In Process | | Х | | | |
| Finished Goods | | X | | | |
| RMA | | X | | | |
| This PCN had been O | IIAI IFIED and APPI | | M Engineerin | ng Department on 12/11/2014. | |
| | | | | 19 Department on 14142014. | |

APPROVED BY

| VP OF SALES <approved></approved> | 02/12/2015 |
|-----------------------------------|------------|
|-----------------------------------|------------|

Date