



# BCM

## Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

<b>PCN Number:</b> P223907		<b>Revision:</b> A		<b>Date of Publication:</b> 09/30/2022
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
OFT10W-3455J-AN	69372	1.0	1.1	Hardware

**REASON OF CHANGE:**  
 Current Infineon SLB9665TT2.0 Trust Platform Module (TPM) 2.0 is highly constrained and severely impacting production lead-time.

**DESCRIPTION OF CHANGE:**  
 Change to use Intel Platform Trust Technology (TCG TPM 2.0).

**IMPACT OF CHANGE AND RECOMMEND ACTION:**  
 This change has been thoroughly evaluated to ensure that there are no quality, regulation or reliability implications to our customer.  
 BCM is not recommending our customer to perform additional qualification of these changes if not using TPM.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**  
 Date: January, 2023  
 OR  
 Lot#:  
 \*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 09/30/2022.  
 This PCN had been **APPROVED** by BCM Procurement Department on September, 2022.

### APPROVED BY

<b>VP OF SALES</b>	<APPROVED>	09/30/2022
--------------------	------------	------------

Signature

Date