

BCM

Product Change Notice

PCN Type: ■HW/SYS	5/Kit ■BIOS/LAN/F	// ⊔Package	e/Label ⊔Dri	ver/OS	⊔Acc.	⊔Others	Page: <u>1</u> of <u>1</u>
PCN Number: H184	Revision: A		Date of Publication: 11/06/2018				
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW REVISION TYPE		TYPE			
RX110H	71172-IA	1.2	2.0	Hardwa	re		

REASON OF CHANGE:

- 1) To be compliant with Microsoft® Windows® 10 Redstone 2 and 3 updates.
- 2) To allow for locking type cable connectors to be used on the GPIO pin-headers.

DESCRIPTION OF CHANGE:

- 1) Trusted Platform Module 2.0 firmware will be updated to FW5.63.
- 2) Update the GPIO pin-header connector to enclose the GPIO pin-headers with a plastic shroud to support locking type pin-header connectors in addition to standard non-locking type connectors.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, functional and regulation implications to our customer.

BCM is not recommending customer to perform additional qualification of this change.

AFFECTED BY T	HIS CHANGE
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: Mar, 2019

OR **Lot#**:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	Χ		
In Process		Х	
Finished Goods		Х	
RMA		Х	

This PCN had been QUALIFIED and APPROVED by BCM Engineering Department on 10/31/2018.

This PCN had been APPROVED by BCM Procurement Department on 11/06/2018.

APPROVED BY

VP OF SALES <approved> 11/06/2018</approved>

Signature Date

Doc#: F-G0-0-006A