

## **BCM Preliminary Product Change Notice**

PCN Number: 70902-B1-001		Revision: A		Date of Publication: 01/21/2014			
PRODUCT NAME	PRODUCT PART#	OLD - RE	<b>/. —</b> NEW		REVISI	ON TYPE	
RX87Q	70902-C	Х	1.00	BIOS			
REASON OF CHAN							
Production Release	for AMI BIOS.						
DESCRIPTION OF	CHANGE:						
File name: 7090210	0 rom						
Message: RX87Q (70 Version#: 1.10	J902) BIOS V1.00						
	1 /						
Build date: 01/17/20 Checksum: B366h	14						
	rmware Update Utility	v2 21 /ofudor o	wo)				
riash Utility. Alvil Fl	iniware opuate office						
	GE AND RECOMMEN						
			t there is no	auality, reliat	oility. functi	onal. thermal	or
This change has bee	en thoroughly evaluate		t there is no	quality, reliat	oility, functi	onal, thermal	or
This change has bee			t there is no	quality, reliat	oility, functi	onal, thermal	or
This change has bee regulation implicati	en thoroughly evaluate ons to our customers.	d to ensure tha					
This change has bee regulation implicati BCM is recommend	en thoroughly evaluate ons to our customers. ing our customers to p	d to ensure tha					
This change has bee regulation implicati BCM is recommend	en thoroughly evaluate ons to our customers.	d to ensure tha					
This change has bee regulation implicati BCM is recommend	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model.	d to ensure tha					
This change has bee regulation implicati BCM is recommend #70901-C (Phoenix	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model.	d to ensure tha					
This change has bee regulation implicati BCM is recommend #70901-C (Phoenix AFFECTED BY TH	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <b>IIS CHANGE</b>	d to ensure tha					
This change has bee regulation implicati BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <b>HIS CHANGE</b> NO	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO NO	d to ensure tha					
This change has bee regulation implicati BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. HIS CHANGE NO NO NO YES	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO NO YES NO	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY The Specification Packaging Labeling BIOS Driver Hardware	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO NO YES NO	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: 03/03/2014 OR	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO NO YES NO	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: 03/03/2014 OR Lot#:	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. HIS CHANGE NO NO YES NO NO NO	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: 03/03/2014 OR Lot#:	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO NO YES NO	d to ensure tha					
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: 03/03/2014 OR Lot#: *Cut in date is base	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO YES NO NO NO d on the current forecas	d to ensure tha	nal qualificat				
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: 03/03/2014 OR Lot#: *Cut in date is based	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. <u>HIS CHANGE</u> NO NO YES NO NO NO d on the current forecas	d to ensure tha erform additior	nal qualificat	tion of these c			
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: 03/03/2014 OR Lot#: *Cut in date is base	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. HIS CHANGE NO NO NO YES NO NO NO d on the current forecas Rework	d to ensure tha erform additior	nal qualificat	tion of these c			
This change has bee regulation implication BCM is recommend #70901-C (Phoenix AFFECTED BY TH Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: 03/03/2014 OR Lot#: *Cut in date is based Parts Disposition New Order	en thoroughly evaluate ons to our customers. ing our customers to p BIOS) to this model. HIS CHANGE NO NO YES NO YES NO NO d on the current forecas Rework X	d to ensure tha erform additior	nal qualificat	tion of these c			

APPROVED BY

VP OF SALES <APPROVED> 01/21/2014

Signature

Date