

RX87Q Firmware updates instruction.

- 1) You may download firmware update provided from BCM website with file name such as 70903xxx.zip, this compress file is included AMI DOS Firmware update utility AFUDOS and a batch file Flash.bat for easy use by typing "Flash" at DOS prompt or you can type in "afudos 7090xxx.ROM /p /b /n" at DOS prompt which xxx refer to actual firmware file name.
- 2) If you decided to use other OS firmware update utilities, you may download AMI firmware update tool from below link and select "FIRMWARE UPDATE TOOL FOR APTIO 4"

<https://ami.com/en/support/bios-uefi-firmware-support/>

A) Read the license agreement and if you agree to the term and condition, go to Submit to continue download firmware update utility, decompress the file to you storage and select which OS firmware update tool you need, be sure you read the instruction manual before process*.

32	[folder]	0 B	0 B	2016-06-27 14:38:04	D....		AMI AFU For Aptio 4\afuefi\32
32	[folder]	0 B	0 B	2016-06-27 14:38:04	D....		AMI AFU For Aptio 4\afuwin\32
64	[folder]	0 B	0 B	2016-06-27 14:38:04	D....		AMI AFU For Aptio 4\afuefi\64
64	[folder]	0 B	0 B	2016-06-27 14:38:04	D....		AMI AFU For Aptio 4\afuwin\64
afudos	[folder]	0 B	0 B	2016-06-27 14:38:04	D....		AMI AFU For Aptio 4\afudos
afuefi	[folder]	0 B	0 B	2016-06-27 14:38:04	D....		AMI AFU For Aptio 4\afuefi
afuwin	[folder]	0 B	0 B	2016-06-27 14:38:04	D....		AMI AFU For Aptio 4\afuwin
afudos.zip	.zip	543.0 KB	543.0 KB	2016-06-27 14:17:26	.R..A	F0AAD8FD	AMI AFU For Aptio 4\afudos\afudos.zip
afuefi32.zip	.zip	1.1 MB	1.1 MB	2017-08-30 11:03:42	.R..A	3698FF47	AMI AFU For Aptio 4\afuefi\32\afuefi32.zip
afuefi64.zip	.zip	1.1 MB	1.1 MB	2017-08-30 11:03:56	.R..A	06D7F1D9	AMI AFU For Aptio 4\afuefi\64\afuefi64.zip
afuwin32.zip	.zip	1.4 MB	1.4 MB	2017-08-30 11:02:30	.R..A	54F92DB0	AMI AFU For Aptio 4\afuwin\32\afuwin32.zip
afuwin64.zip	.zip	1.5 MB	1.5 MB	2017-08-30 11:03:00	.R..A	F808EB65	AMI AFU For Aptio 4\afuwin\64\afuwin64.zip
software-license-agreement.txt	.txt	8.2 KB	3.2 KB	2016-06-27 14:21:22A	F4FC5391	AMI AFU For Aptio 4\software-license-agreement.txt

- Improper procedure for firmware update may result to firmware corruption which might cause system not power up properly.
- BCM will not be responsible for any wrong doing of firmware update that might result on firmware corruption.