



BCM

Product Change Notice

PCN Type : Hardware BIOS/Firmware Test Driver Others Page: 1 of 1

PCN Number: 70601-B1-004 Revision: A Issued Date: 5/13/2009

Drawing Number	OLD—REV.--NEW		TITLE	MODEL
70601	1.02	1.03	BC35Q (#70601) BIOS	BC35Q (BCM/US)

REASON:

1. Correct E8600 CPU shut down issue in WinXP.
2. Add support for OEM logo feature.
3. Add support for QX9650, E8400 CPU.

DESCRIPTION OF CHANGE:

BC35Q (#70601) BIOS release:

1. File Name: 70601103.ROM
2. BIOS VER: 1.03
3. BIOS DATA: 5/06/2009
4. BIOS Checksum: 4CB1 hex (1MB)
5. Post Message: BC35Q BIOS VER 1.03

SPECIAL INSTRUCTIONS:

CLASS OF CHANGE	AFFECTED BY THIS CHANGE			PARTS DISPOSITION	REWORK	USE AS	SCRAP	EFFECTIVITY
V A-MANDATORY	V REC INSPECTION		TEST EQUIP.	NEW ORDER		V		DATE: OR LOT: 0923 OR SERIAL No.: _____
B-RECORD	TEST PROCEDURES		TOOLING	IN PROCESS		V		
C-DEVIATION	MFG. RWK. INSTR.			FINISHED GOODS		V		
Project Control Number: 70601-B1-004				CUSTOMER				
				RMA	V			

Originator: William Huang Department: Engineering Phone: 949-470-1888 Ext. 273 Date: 5/13/2009

Department	Signatures	Date	Department	Signatures	Date
PROJECT ENGINEER	William Huang	5/13/2009	ACCOUNT MANAGER	Jennifer Morris	5/13/2009
ENGINEERING MANAGER	Laurent Liu	5/13/2009			
PROGRAM MANAGER	William Huang	5/13/2009			