



# BCM


## Product Change Notice

PCN Type:  HW/SYS/Kit  BIOS/LAN/FW  Package/Label  Driver/OS  Acc.  Others Page: 1 of 1

<b>PCN Number:</b> 71001-H1-007/ 69036-S1-005		<b>Revision:</b> A		<b>Date of Publication:</b> 07/18/2017
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
MX1900J	71001-IA	1.4A	1.4B	Hardware
BI255-1900J	69036	1.3	1.3A	

**REASON OF CHANGE:**  
To improve the battery adhesive on the MX1900J board.

**DESCRIPTION OF CHANGE:**  
Change the battery adhesive location on the PCBA to next to the SATA port.



**IMPACT OF CHANGE AND RECOMMEND ACTION:**  
This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal or regulation implications to our customers.  
BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**  
Date: July, 2017  
OR  
Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 07/18/2017.

**APPROVED BY**

VP OF SALES	<APPROVED>	07/18/2017
-------------	------------	------------

**Signature**

**Date**