



# BCM

## Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

<b>PCN Number:</b> 71142-B1-002		<b>Revision:</b> A		<b>Date of Publication:</b> 01/09/2017
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
MX3160N	71142-IA	1.00	1.01	BIOS

**REASON OF CHANGE:**

Roll in Intel patch for fixing

- \* USB3 Detection Issue with Certain USB3 Devices.
- \* USB3 Devices Intermittent Link Train Issue during Warm Reboot Cycling.
- \* USB2 Increased Eye Pattern Height Issue.

**DESCRIPTION OF CHANGE:**

File name: 71142101.ROM  
 BIOS msg: MX3160N #71142 BIOS V1.01  
 BIOS ver: 1.01  
 BIOS checksum: ADD6 hex

**IMPACT OF CHANGE AND RECOMMEND ACTION:**

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal, driver or regulation implications to our customer.

BCM is not recommending our customer to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

**CUT IN DATE:**

Date: March, 2017

OR

Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA	X		

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 12/09/2016.

**APPROVED BY**

<b>VP OF SALES</b>	<APPROVED>	01/09/2017
--------------------	------------	------------

Signature

Date