



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: P204001		Revision: A		Date of Publication: 10/01/2020
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX3160N	71142-IA	2.2	2.3	Hardware

REASON OF CHANGE:

Improve compatibility with a broader range of power supplies and power adapters.

DESCRIPTION OF CHANGE:

Change resistor value on location OR31 to 470Ω and locations OR34 and OR35 to 330Ω.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customer.

BCM is not recommending our customer to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: Feb, 2020
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 09/30/2020.
This PCN had been **APPROVED** by BCM Procurement Department on October, 2020.

APPROVED BY

VP OF SALES	<APPROVED>	10/01/2020
--------------------	------------	------------

Signature

Date