



# BCM

## Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others Page: 1 of 1

<b>PCN Number:</b> 71211-H1-005		<b>Revision:</b> A		<b>Date of Publication:</b> 01/19/2011
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW	<b>REVISION TYPE</b>	
MX45GM	71211	2.0	2.1	Hardware Revision

### REASON OF CHANGE:

Change the compact flash socket on the bottom of the MX45GM industrial motherboard to a low profile type. This will allow the MX45GM to be compatible with a wider variety of standard mini ITX chassis where the chassis motherboard mounting standoffs are not tall enough to accommodate a standard sized compact flash socket.

### DESCRIPTION OF CHANGE:

Change CF socket from 8.6mm to 5.6mm.



### IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.

BCM is not recommending the customers to perform the additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

### CUT IN DATE:

Date:  
OR  
Lot#: 1111

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 01/06/2011.

**APPROVED BY**

<b>CUSTOMER/ VP OF SALES</b>	<APPROVED>	01/19/2011
----------------------------------	------------	------------

**Signature**

**Date**

