



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others Page: 1 of 1

PCN Number: 71211-H1-006		Revision: A		Date of Publication: 05/06/2011
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX45GM	71211-C	2.1	2.2	Hardware Revision

REASON OF CHANGE:
 Improve compatibility with a wider range of DC power sources.

DESCRIPTION OF CHANGE:
 Add a 10µF 6.3V capacitor in between CLRTC1 pin 1 (VCCRTC) and Ground pin on PCI1.

IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.
 BCM is not recommending the customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:
 Date: 05/23/2011
 OR
 Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods	X		
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 05/06/2011.

APPROVED BY

CUSTOMER/ VP OF SALES	<APPROVED>	05/06/2011
----------------------------------	------------	------------

Signature

Date