



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others

Page: 1 of 1

PCN Number: 70821-H1-002		Revision: A		Date of Publication: 07/11/2012
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX67QMD	70821-C	1.0A	1.1	Hardware

REASON OF CHANGE:
Change COM port jumper settings defaults to 5V versus 12V.

DESCRIPTION OF CHANGE:
Change jumper cap pin selection to 5V.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.
BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:
Date: 09/21/2012
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 07/11/2012.

APPROVED BY

CUSTOMER/ VP OF SALES	<APPROVED>	07/11/2012
----------------------------------	------------	------------

Signature

Date