



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others

Page: 1 of 1


PCN Number: P123101		Revision: A		Date of Publication: 07/30/2012	
PRODUCT NAME	PRODUCT PART#	OLD	REV.	NEW	REVISION TYPE
BC206C	70812-C	1.0		1.0	Hardware
BC67Q	70811-C	1.0		1.0	Hardware
MX67QM	71321-C	1.1		1.1	Hardware
MX67QM-QC	71323	1.0		1.0	Hardware
MX67QMD	70821-C	1.1		1.1	Hardware
MX67QMD-LC	70822	0.1		0.1	Hardware
RX67Q	71311-C	1.0A		1.0A	Hardware
RX67QV	71312-C	1.0		1.0	Hardware
RX67QV-LC	71313-C	1.0		1.0	Hardware
RX67QS	71314-C	0.1		0.1	Hardware
SBC65HM	75361	1.0		1.0	Hardware
BOX65HM-V	69258	1.0		1.0	Hardware

REASON OF CHANGE:


Platform Controller Hub (PCH) chipsets may see a visual change with brownish/ yellowish stain. Refer to Intel Product Change Notification (PCN) # 111650-00.

DESCRIPTION OF CHANGE:

Current



New



IMPACT OF CHANGE AND RECOMMEND ACTION:

Since there is no change to the form, fit or function of the products according to vendor's PCN, BCM will not evaluate this change.

BCM is not recommending additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: Running Changes

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 07/30/2012.

APPROVED BY

CUSTOMER/ VP OF SALES	<APPROVED>	07/30/2012
----------------------------------	------------	------------

Signature

Date