



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 71001-H1-005/ 69036-S1-005		Revision: A		Date of Publication: 02/12/2015
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX1900J	71001-IA	1.2	1.3	Hardware
BI255-1900J	69036	1.0	1.1	

REASON OF CHANGE:
Disconnect unused pin on Intersil component ISL95837 from the MX1900J motherboard circuitry.

DESCRIPTION OF CHANGE:
Remove resistor from location PPR9.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, driver or thermal implications to our customers.
BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:
Date: June, 2015
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 02/11/2015.

APPROVED BY

VP OF SALES	<APPROVED>	02/12/2015
--------------------	------------	------------

Signature

Date