



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 70961-B1-002		Revision: A		Date of Publication: 11/03/2015
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX280NI	70961-IA	1.01	1.02	BIOS

REASON OF CHANGE:

- 1) Correct typo within the LVDS panel selection field in BIOS.
- 2) Fix Ubuntu Operating System version 14.04.2 installation issue.
- 3) Fix display port issue in which the display is blank after loading into some Operating Systems.

DESCRIPTION OF CHANGE:

File name: 70961102.ROM
 Message: MX280NI #70961 BIOS V1.02
 Version: 1.02
 Date: 10/29/2015
 Checksum: 196F hex
 Flash Utility: Built into the UEFI BIOS

IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there are no quality and driver implications to our customers. BCM is not recommending customers to perform additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

CUT IN DATE:
 Date: 12/21/2015
 OR
 Lot#:
 *Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 10/29/2015.

APPROVED BY

VP OF SALES	<APPROVED>	11/03/2015
--------------------	------------	------------

Signature

Date