

BCM

Product Change Notice

PCN Number: P251801		Revision: A		Date of Publication: 04/28/2025	
PRODUCT NAME	PRODUCT PART#	OLD — REV	. — NEW	REVISION TYPE	
MX610HD	71852-IA	1.1	1.2	Hardware	
MX610HD-BB33	71855-IA	1.1	1.2		
REASON OF CHANC	SE:				
	4402P and PJQ4444F	PMOSFET have b	peen discont	tinued.	
DESCRIPTION OF C					
-				cation: PQ6, PQ7 and PQ10.	
•	PJQ4401P to PANJIT P				
•				cation: PQ11 and PQ8.	
•				QDBZR Regulator on location: PU8.	
Change from on 100p	F to 680pF Capacitor	on location: PC	417.		
	E AND RECOMMEN				
-				quality, functional, or compliance implication	ons
our customers. BCM	is not recommending	customers to p	erform addi	tional qualifications of this change.	
AFFECTED BY THI Specification	NO				
Packaging	NO				
Labeling	NO				
BIOS	NO				
Driver					
Hardware	NO				
	YES				
Date: 04/28/2026 OR					
Lot#:					
*Cut in date is based	on the current foreca	st.			
Parts Disposition	Rework	As Is		Scrap	
New Order	Х				
		Х			
In Process		Х			
Finished Goods					
		Х			
Finished Goods RMA	UALIFIED and APP		l Engineerin	g Department on April, 2025.	

APPROVED BY

CUSTOMER/ VP OF SALES <a a="" href="https://www.example.com" www.example.com"="" www.example.com<=""> <a a="" href="https://www.example.com" www.example.com"="" www.example.com<=""> <a a="" href="https://www.example.com" www.example.com"="" www.example.com<="">
--

Signature

Date