



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 2

PCN Number: P214401		Revision: D		Date of Publication: 09/22/2022
PRODUCT NAME	PRODUCT PART#	OLD HW / BIOS	REV. — NEW HW / BIOS	REVISION TYPE
MX110H	71152-IA	1.4/ 1.30	1.5/ 1.50	
MX3160N	71142-IA	2.4/ 2.30	2.5/ 2.50	
MX3350N	71524-IA	2.4/ 3.10	2.5/ 3.20	
MX3940E	71523	2.2/ 1.20	2.3/ 1.30	
RX110H	71172-IA	2.2/ 1.30	2.3/ 1.50	
RX110H-OC	71173-IA	2.3/ 1.30	2.4/ 1.50	
RX170Q	71163-IA	1.3/ 1.60	1.4/ 1.70	

REASON OF CHANGE:

Intel Ethernet Controller I211AT is End of Life (Refer to Intel Change Notification #: 118543-00) and anticipated future supply is no longer predictable

DESCRIPTION OF CHANGE:

Change to use Intel Ethernet Controller I210AT.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customer. BCM is recommending customers to perform additional qualification of these changes if using PXE Boot and not using the Intel PROSet Driver.

AFFECTED BY THIS CHANGE	
Specification	YES
Packaging	NO
LAN Image	YES
BIOS	YES
Driver	NO*
Hardware	YES

*If using Intel PROSet Driver, doesn't require to re-install the driver.

CUT IN DATE:

Date: March, 2023

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on November, 2021.

This PCN had been **APPROVED** by BCM Procurement Department on November, 2021.

APPROVED BY

VP OF SALES	<APPROVED>	09/01/2022
--------------------	------------	------------

Signature

Date