



# BCM

## Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others Page: 1 of 1

<b>PCN Number:</b> 70771-H1-002		<b>Revision:</b> A		<b>Date of Publication:</b> 02/22/2012
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
RX45Q	70771-C	1.0	1.1	Hardware Revision

**REASON OF CHANGE:**  
 Realtek audio codec ALC888 will be phased out due to product end of life and replaced by the Realtek audio codec ALC886.

**DESCRIPTION OF CHANGE:**  
 Add Realtek audio codec ALC886 to the approved vendor list (AVL). The ALC886 and ALC888 are hardware pin-to-pin compatible and will require no layout change to the motherboard.

**IMPACT OF CHANGE AND RECOMMEND ACTION:**  
 This change has been thoroughly evaluated to ensure that there are no quality and reliability implications to our customers.  
 If the customer is using Microsoft® Windows® OS, BCM recommends updating audio driver to version R2.53 (5.10.0.6215) or above. It is recommended that the customer evaluates this new hardware changes to ensure smooth transition.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**  
 Date: 09/03/2012  
 OR  
 Lot#:  
 \*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 02/22/2012.

**APPROVED BY**

<b>CUSTOMER/ VP OF SALES</b>	<APPROVED>	02/22/2012
----------------------------------	------------	------------

Signature

Date