



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver OS Others Page: 1 of 1

| | | | | |
|---|----------------------|-------------------------|-----|--|
| PCN Number: 71311-H1-003/ 71312-H1-003/ 71313-H1-003/ 71314-H1-003/ 71315-H1-003 | | Revision: A | | Date of Publication: 04/03/2014 |
| PRODUCT NAME | PRODUCT PART# | OLD — REV. — NEW | | REVISION TYPE |
| RX67Q | 71311-C | 1.1 | 1.2 | Hardware |
| RX67QV | 71312-C | 1.0 | 1.1 | |
| RX67QV-LC | 71313-C | 1.0 | 1.1 | |
| RX67QS | 71314-C | 1.0 | 1.1 | |
| RX67Q | 71315-C | 1.0 | 1.1 | |

REASON FOR CHANGE:

The capacitor at location C92 is in too close of a proximity to the adjacent eSATA/USB port connectors. This close proximity creates the potential for a mechanical or electrical conflict under certain conditions.

DESCRIPTION OF CHANGE:

Remove capacitor at location C92.

IMPACT OF CHANGE AND RECOMMEND ACTION:

The function of C92 is related to emissions headroom for USB01 and does not have any impact on functionality. Removing this component has had no measurable impact on emission levels. Thorough testing has confirmed this change has no effect on quality, reliability, or functional implications to our customers.

BCM is not recommending customers to perform additional qualification of this change.

| AFFECTED BY THIS CHANGE | |
|-------------------------|-----|
| Specification | NO |
| Packaging | NO |
| Labeling | NO |
| BIOS | NO |
| Driver | NO |
| Hardware | YES |

CUT IN DATE:

Date: 04/14/2014
OR
Lot#:

*Cut in date is based on the current forecast.

| Parts Disposition | Rework | As Is | Scrap |
|-------------------|--------|-------|-------|
| New Order | X | | |
| In Process | X | | |
| Finished Goods | | X | |
| RMA | X | | |

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 03/20/2014.

APPROVED BY

| | | |
|--------------------|------------|------------|
| VP OF SALES | <APPROVED> | 04/03/2014 |
|--------------------|------------|------------|

Signature

Date

