



# BCM

## Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

<b>PCN Number:</b> 70903-B1-003		<b>Revision:</b> A		<b>Date of Publication:</b> 04/29/2015
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
RX87Q	70903-C	1.01	1.20	BIOS

**REASON OF CHANGE:**

- 1) Fix PS/2 keyboard issue where it cannot enter the BIOS setup menu when the keyboard Num Lock is set to off.
- 2) Improve SATA Drive detection for a broader range of SSD drives.

**DESCRIPTION OF CHANGE:**

File name 70903120.rom  
 Message: RX87Q (70903) BIOS V1.20  
 Version: 1.20  
 Build Date: 04/08/2015  
 Checksum: EC70 hex  
 Flash Utility: AMI Firmware Update Utility v2.31 (afudos.exe)

**IMPACT OF CHANGE AND RECOMMEND ACTION:**

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional or driver implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

**CUT IN DATE:**

Date: June, 2015  
 OR  
 Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 04/15/2015.

**APPROVED BY**

<b>VP OF SALES</b>	<APPROVED>	04/29/2015
--------------------	------------	------------

**Signature**

**Date**