



# BCM

## Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

<b>PCN Number:</b> 70903-L1-002		<b>Revision:</b> A		<b>Date of Publication:</b> 10/31/2017
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
RX87Q	70903-C	1.00	1.01	LAN1 (i217-LM) Image

**REASON OF CHANGE:**  
 Fix security vulnerability issue that may cause Intel DAL failures that may impact Intel Identity Protection Technology and True Key functionalities. (Documented in Intel CVE-2017-5689).

**DESCRIPTION OF CHANGE:**  
 Update LAN1 Image to 1.01.

**IMPACT OF CHANGE AND RECOMMEND ACTION:**  
 This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal or regulation implications to our customers.  
 BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
Firmware	YES
Driver	NO
Hardware	NO

**CUT IN DATE:**  
 Date: Nov, 2017  
 OR  
 Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 10/31/2017.

**APPROVED BY**

<b>VP OF SALES</b>	<APPROVED>	10/31/2017
--------------------	------------	------------

Signature

Date