

# **BCM**

# **Product Change Notice**

Г	20NIN I D204402	_		<b>D</b> 4	<u> </u>	11 10/00	/2020				Ī
F	PCN Type: □HW/SYS/Kit	■BIOS/LAN/FW	□Package/Label	□Driver/OS	□Acc.	□Others	Page:	1	of	2	

PCN Number: P204403		Revision: A		Date of Publication: 10/29/2020	
PRODUCT NAME	PRODUCT PART#	OLD — RE	<b>V.</b> — NEW	REVISION TYPE	
BC246C	71586-IA	1.10	1.11	BIOS	
BC370Q	71582-IA	1.10	1.11		

#### **REASON OF CHANGE:**

Improve compatibility with a broader range of ATX power supplies and their variances in voltage bring-up timings.

#### DESCRIPTION OF CHANGE:

File name 71582111.ROM

Message: BC370Q #71582 BIOS V1.11 File date/ time: 10/18/2020 7:36:46 PM

Checksum: 1CEC hex

Programming Method: AMIFWUpdate/ AMI Firmware Update under BIOS menu

File name: 71586111.ROM

Message: BC246C #71586 BIOS V1.11

Version: 1.11

File date/ time: 10/18/2020 8:30:19 PM

Checksum: F17E hex

Programming Method: AMIFWUpdate/ AMI Firmware Update under BIOS menu

### IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customer.

BCM is not recommending our customer to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

#### **CUT IN DATE:**

Date: January, 2021

OR **Lot#**:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	Х		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 10/23/2020.

This PCN had been **APPROVED** by BCM Procurement Department on October, 2020.

## **APPROVED BY**

VP OF SALES <approved> 10/29/2020</approved>
--

Signature Date

Doc# : F-G0-0-007A