



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 71152-H1-003/ 71172-H1-002		Revision: A		Date of Publication: 11/13/2017
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX110H	71152-IA	1.0	1.1	Hardware
RX110H	71172-IA	1.0	1.1	

REASON OF CHANGE:
To utilize full advantages of Infineon Trusted Platform Modules (TPM) 2.0 hardware security for RSA key generation.

DESCRIPTION OF CHANGE:
Update TPM2.0 from firmware 5.51 to 5.62.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or thermal implications to our customers.
BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:
Date: Jan, 2018
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 11/13/2017.

APPROVED BY

VP OF SALES	<APPROVED>	11/13/2017
--------------------	------------	------------

Signature

Date