

BCM

Product Change Notice

PCN Type: ■HW/SYS/Kit	□BIOS/LAN/FW	■Package/Label	□Driver/OS	■Acc.	□Others	Page:	<u>1</u> of	<u>1</u>

PCN Number: 71131-H1-003		Revision: A		Date of Publication: 05/26/2016	
PRODUCT NAME	PRODUCT PART#	OLD — RE	V. — NEW	REVISION TYPE	
MX170QD	71131-IA	1.1	1.2	Hardware/ Labeling/ Accessory	

REASON OF CHANGE:

- 1) Update package labels to comply with the latest regulations.
- 2) Add support for Deep S5 power state.

DESCRIPTION OF CHANGE:

- 1) Add new labels and caution guides to the outer packaging cartons in compliance with the latest IATA regulatory requirements.
- 2) Update BOM to add and change resistor locations: SR4 and R475.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal or regulation implications to our customers.

BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE				
Specification	YES			
Packaging/ Accessory	YES			
Labeling	YES			
BIOS	NO			
Driver	NO			
Hardware	YES			

CUT IN DATE:

Date: Nov, 2016

OR Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	Χ		
In Process		Х	
Finished Goods		Х	
RMA		Χ	

This PCN had been QUALIFIED and APPROVED by BCM Engineering Department on 08/16/2016.

APPROVED BY

VP OF SALES	<approved></approved>	08/30/2016

Signature Date

Doc#: F-G0-0-005G