



# BCM

## Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver OS Others Page:  1  of  1

<b>PCN Number:</b> 70961-H1-004		<b>Revision:</b> A		<b>Date of Publication:</b> 05/06/2014
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
MX280NI	70961-IA	1.2	1.3	Hardware

### REASON OF CHANGE:

- 1) Meet UL requirement.
- 2) Improve the absorption of vibration.

### DESCRIPTION OF CHANGE:

- 1) Update PCB silkscreen to indicate UL recognized mark.



- 2) Add Battery warning guide.
- 3) Add UL recognized mark on the carton label.



- 4) Add thermal pad on the choke.

### IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal or regulation implications to our customers.

BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**

Date: 09/22/2014

OR

Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 05/06/2014.**APPROVED BY**

VP OF SALES	<APPROVED>	05/06/2014
-------------	------------	------------

Signature

Date