



# BCM

## Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 2

<b>PCN Number:</b> P221801		<b>Revision:</b> B		<b>Date of Publication:</b> 05/18/2022
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD —	REV. —	NEW
MX3160N	71142-IA	2.4	2.5	Hardware
		2.30	2.30A	BIOS

**REASON OF CHANGE:**

Current Infineon SLB9665TT2.0 Trust Platform Module (TPM) 2.0 is in long lead time.

**DESCRIPTION OF CHANGE:**

Change to use Intel Platform Trust Technology (TCG TPM 2.0).

File Name: 71142230A.ROM  
 Message: MX3160N #71142 BIOS V2.30A  
 Checksum: 0B58 hex  
 Remark: Can only use on v2.5 or above only.

**IMPACT OF CHANGE AND RECOMMEND ACTION:**

BCM is recommending our customer to perform additional qualification of this changes if using TPM.

AFFECTED BY THIS CHANGE	
Specification	YES
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO**
Hardware	YES

\*\*With Microsoft Windows 10 and 11 Operating System.

**CUT IN DATE:**

Date: July, 2022  
 OR  
 Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on May, 2022.  
 This PCN had been **APPROVED** by BCM Procurement Department on May, 2022.

**APPROVED BY**

<b>VP OF SALES</b>	<APPROVED>	05/18/2022
--------------------	------------	------------

**Signature**

**Date**