



# BCM

## Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others

Page: 1 of 1


<b>PCN Number:</b> 71251-P1-002		<b>Revision:</b> A		<b>Date of Publication:</b> 09/29/2011
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
MX45GM2	71251-C	1.0	1.0A	Package Revision

**REASON OF CHANGE:**

Add 2<sup>nd</sup> source of CPU Cooler.

**DESCRIPTION OF CHANGE:**

The new 2<sup>nd</sup> source of CPU Cooler will have slightly different on the heatsink. There is no change on CPU Fan.



**IMPACT OF CHANGE AND RECOMMEND ACTION:**

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.

BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	YES
Labeling	NO
BIOS	NO
Driver	NO
Hardware	NO

**CUT IN DATE:**

Date: 10/10/2011

OR

Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 09/27/2011.**APPROVED BY**

CUSTOMER/ VP OF SALES	<APPROVED>	09/29/2011
--------------------------	------------	------------

Signature

Date