



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others Page: 1 of 1

PCN Number: 71321-P1-002/ 70821-P1-002		Revision: A		Date of Publication: 07/11/2012
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX67QM	71321-C	1.0	1.0A	Accessories
MX67QMD	70821-C	1.0	1.0A	Accessories

REASON OF CHANGE:
Extend the length of the accessory cables and SATA cable and orientation to be more accommodating for various chassis and system enclosures.

DESCRIPTION OF CHANGES:

- 1) **Both MX67QM and MX67QMD:** Change SATA data cable orientation from (90 degree - 180 degree) to straight (180 degree - 180 degree).
- 2) **MX67QMD Only:** Extend the length of the SATA power cable from 7" to 11".
- 3) **MX67QMD Only:** Extend the length of the DC power cable from 7" to 12".

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.
BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	YES
Labeling	NO
BIOS	NO
Driver	NO
Hardware	NO

CUT IN DATE:
Date: 09/21/2012
OR
Lot#:
*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 07/11/2012.

APPROVED BY

CUSTOMER/ VP OF SALES	<APPROVED>	07/11/2012
	Signature	Date

