



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver OS Others Page: 1 of 1

PCN Number: 71321-H1-006/ 71322-H1-004/ 70821-H1-005		Revision: A		Date of Publication: 04/24/2013
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX67QM	71321-C	1.3	1.4	Hardware
MX67QMU	71322-C	1.2	1.3	
MX67QMD	70821-C	2.1	2.2	

REASON OF CHANGE:
Improve compatibility with various DVI and HDMI monitors.

DESCRIPTION OF CHANGE:
Change from 10uH to 100nH inductor on locations: L46 and L47.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal, driver or UL certification implications to our customers.
BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: 05/27/2013

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 04/23/2013.

APPROVED BY

VP OF SALES	<APPROVED>	04/24/2013
--------------------	------------	------------

Signature

Date