



BCM

Product Change Notice

PCN Type : Hardware BIOS/Firmware Test Driver Others Page: 1 of 1

PCN Number: 70541-H1-003			Revision: A	Issued Date: 06/15/2009
Drawing Number	OLD—REV.--NEW		TITLE	MODEL
70541-001	1.1	1.2	PWA	RX965Q (BCM/US)

REASON:

- Remove IDE support from the RX965Q motherboard due to the EOL of the USB-IDE bridge chip part number JM20335 (location "U22") from manufacturer JMICRON. Because IDE is not natively support by the Intel Q965 chipset the USB-to-IDE bridge chip was used to support this feature.

DESCRIPTION OF CHANGE:

- The USB-IDE bridge chip "JM20335" (location "U22") will not be populated on RX965Q board.
- The IDE pin-header "IDE1" will not be populated on RX965Q board.
- The components used on the circuitry for supporting "U22" and "IDE1" will not be populated.

SPECIAL INSTRUCTIONS:

CLASS OF CHANGE	AFFECTED BY THIS CHANGE			PARTS DISPOSITION	REWORK	USE AS	SCRAP	EFFECTIVITY
V	A-MANDATORY	REC INSPECTION	TEST EQUIP.	NEW ORDER	V			DATE: July 2009
	B-RPCNRD	TEST PROCEDURES	TOOLING	IN PROCESS	N/A			OR
	C-DEVIATION	MFG. RWK. INSTR.		FINISHED GOODS	N/A			LOT:
Project Control Number: 70541-H1-003				CUSTOMER	N/A			OR
				RMA	N/A			SERIAL No.: _____

Originator: William Huang Department: Engineering Phone: 949-470-1888 Ext. 273 Date: 06/15/2009

Department	Signatures	Date	Department	Signatures	Date
PROJECT ENGINEER	William Huang	06/15/2009	ACCOUNT MANAGER	Jennifer Morris	06/15/2009
TECHNICAL MANAGER	Laurent Liu	06/15/2009			
PROGRAM MANAGER	William Huang	06/15/2009			